



## PRODUCT SUPPORT BULLETIN NO. 214A

DATE: August 31, 1995

MACHINE: **AUTO-LIFTS, All Serial Numbers**

PRODUCTION

DATES: 3/88 through Present

SUBJECT: Chain Tightener

A second Chain Tightener Kit has been developed to replace the 2145 6525 Idler Brackets on the Auto-Lifts.

This chain tightener is accessible from the top of the frame (does not require getting under the machine). By loosening a capscrew and using a wrench as a lever, the chain can be set to the desired tightness by pressing the lever arm into the chain and then retightening the capscrew to hold the lever arm in place. See Figure.

This kit, **9679 0165, Chain Tensioner Assembly**, contains all necessary parts and hardware for installation and installation drawings/instructions. Please contact your Nordco Representative or Nordco Parts Sales for ordering information and availability.

